
Smoke and Dye Testing Summary

High Level Sewershed

| Run Summar | у | | | | | | |
|------------|-----------|-------------------|---------------------|-------------|---------------------|-----------------------|-----------------|
| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
| S1028-075 | Smoke | 9/10/2008 | ADS/TM | S13AA1014MH | Dry | Yes | 669.97 |



Smoke and Dye Testing Summary

High Level Sewershed

| Run Summar | y ——— | | | | | | |
|------------|-----------|-------------------|---------------------|-------------|---------------------|-----------------------|-----------------|
| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
| S1028-075 | Smoke | 9/10/2008 | ADS/TM | S13AA1014MH | Dry | Yes | 669.97 |

| Isolated Pipes — | | | | | | |
|------------------|-------------|-------------|---------------|----------------|------------------|--|
| | Pipe ID | Upstream MH | Downstream MH | Length (ft) | Diameter (In) | |
| | S13AA1026G1 | S13AA1026MH | S13AA1005MH | 199.4614 | 8 | |
| | S13AA1005G1 | S13AA1005MH | S13AA1014MH | 225.2292 | 8 | |
| | S13AA1014G1 | S13AA1014MH | S13AA1002MH | 165.7669 | 8 | |
| | S13AA1030G1 | S13AA1030DE | S13AA1014MH | 79.51505 | 8 | |
| | | | | | | |

Observations & Photos

Obs_ID S1028-075-OB01 **Address** 2806 Springhill Ave

Status Private **Source** Other

Location Other

Nearest MH S13AA1014MH

Comments Smoke from basement of abandoned house.

2806 Springhill Ave.

Picture \S1028-075-OB01-P01.jpg

Comments Front of house, 2806 Springhill

Ave.

Obs_ID S1028-075-OB02 **Address** 2804 Springhill Ave

Status Private **Source** Cleanout

Location Yard - front **Nearest MH** S13AA1014MH

Comments Smoke from cleanout in front yard. 2804

Springhill Ave.



Picture \S1028-075-OB02-P01.jpg

Comments Front of house, 2804 Springhill

Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary Date Total Ground **Notification** Company / **Test ID Test Type Inspected Blower MH** Condition Length Made? Super. S1028-075 Smoke 9/10/2008 ADS/TM S13AA1014MH Dry Yes 669.97

Obs_ID S1028-075-OB03

Address Springhill Ave & Towanda Ave

Status Public

Source Storm Manhole

Location Paved asphalt

Nearest MH \$13AA1014MH

Comments Smoke from storm manhole on NE corner of

Springhill Ave & Towanda Ave



Picture \S1028-075-OB03-P01.jpg

Comments Springhill Ave & Towanda Ave

looking northeast